



QUESTAR QM 1 & QM 100 MICROSCOPE SERVICE & REPAIR

STANDARD SERVICE

Basic inspection of mechanical and optical components.
Disassemble control box, clean, and re-grease moving parts.
Clean control box optics
Remove and clean prism/beam splitter
Remove and clean main system optics
Check and adjust optical centering
Resolution check and Video printout
Check and adjust image shift
Check and repair baffle system
Clean E/Ps (1x) - surface clean and cap
Wipe down, buff polished parts, and wax scope
Final inspection

Standard service usually takes 2-4 weeks after approval is given, assuming there is no backlog of instruments to be serviced.

Diagnostic and Minimum Service Fee	\$125.00 plus shipping
Ser-301 QM 1	\$475.00 plus shipping
Ser-303 QM 100	\$550.00 plus shipping
Ser-831 QM SZ Series	\$695.00 plus shipping

Instruments should be carefully packaged in their original or other suitable container and forwarded to us by fully insured U.P.S. PLEASE DO NOT INCLUDE ACCESSORIES. Please include a note and daytime phone number. For international returns, please follow the return procedure described on the Return Merchandise Authorization.

Please call to make an appointment for service and obtain a Return Authorization Number (RMA).

Our Shipping Address is **Questar Corporation**
6204 Ingham Road
New Hope, PA 18938 USA

You can contact us via
Telephone: 215-862-5277 or 800-247-9607
Fax: 215-862-0512
Email: questar@QuestarCorporation.com
Web: www.QuestarCorporation.com

Prices subject to change without notice – effective November 2008
All printed materials are copyright 2008 by Questar Corporation